


Rev. A		Control Number XXXXXXXXXXXX
Effective Date 6/23/2010	T701 versus CT5.1	Page 1/1
Revised Date 6/23/2010	Approved by Bill Baier	Prepared by Kevin Oeltjenbruns

PURPOSE

To explain the differences between the consoles on the T701 versus the CT5.1 (any T701 needing a console replacement will receive a CT5.1 console).

T701 versus CT5.1

Between the T701 production and the CT5.1 production there was a change made involving the bottom overlay, faceplate, and console shell. The old faceplate and the bottom overlay (on the T701) had a cutout, the new faceplate and bottom overlay (on the CT5.1) do not have this cutout. In addition to those 2 parts, the shell, reed switch, and safety key were changed. To correctly replace a T701 console, a complete CT5.1 console set and safety key need to be sent. The pictures below show a CT5.1 console.

