

## Owner's Guide – Correction: USB Port



Date Prepared: 12/9/2016	Models Affected: Elite T7 (TM475)
-----------------------------	--------------------------------------

The USB port on the Elite T7 console is only used for software updates.

The original Operation Guide listed that the USB port can be used to power devices, but that is incorrect. The guide has been corrected in Online Remedy, but the error will remain in printed copies.

---

Revision Date: 5/25/2018 | Revised by: EM