

Owner's Guide – Correction: No ESM



Date Prepared: 11/25/2014	Models Affected: CT9.3 (TM444B), T303 (T444)
------------------------------	---

Energy Saver Mode (ESM) is not available on either the T303 or the CT9.3.

The original owner's manual contained a misprint that listed ESM as a feature on these treadmills. The owner's manual has been corrected in Online Remedy, but the error will remain in printed copies.

Revision Date: 3/23/2018 | Revised by: EM