

TREADMILL MODELS AND ASSOCIATED MOTOR & MCB (Before new MCB label changes)							
Treadmill Models	Motor Model	Motor CHP rating	Motor SAP #	MCB SAP#	Auto Calibration?	Analog or Digital?	E1/E2 Error Code?
400T 715T Plus	JM15-003	1.50	063739-Z	New 1.5 - 2.0HP (no incline) 1000203404 No proposed label change: (1.5 - 2.0HP)	Yes	Analog	Yes
725T Plus	JM15-003	1.50	063739-Z	New 1.5 - 2.0HP (incline) 1000111068 Proposed label change: (1.5 - 2.25HP)	Yes	Analog	Yes
611T 621T	JM15-001 JM15-003	1.25 1.50	063746-Z 063739-Z	Early low cost 1.5HP (incline) 039679-AA	Yes	Analog	No
Evolve - SG Evolve - CT	JM15-003 JM15-001	1.50 1.25	063739-Z 063746-Z	Early low cost 1.5HP (no incline) 098847	No	Analog	No
T100 T200 2010 T101 T101 - 03 632T CT5.2 CT5.3	JM05-017 JM05-017 JM05-015 JM05-015 JM05-015 JM05-015 JM05-015	1.75 1.75 2.25 2.25 2.25 2.25 2.25	016172-Z 016172-Z 1000106039 1000106039 1000106039 1000106039 1000106039	New 1.5 - 2.0HP 1000111068 Proposed label change: (1.5 - 2.25HP)	Yes	Analog	Yes
T202 T203 CT7.1 CT9.1SM 3.1AT LS8.0T LS10.0T LS8.0T - C1 LS10.0T - C1	JM01-013 JM01-015 JM01-013 JM01-015 JM01-015 JM01-013 JM01-015 JM01-013 JM01-015	2.50 2.75 2.50 2.75 2.75 2.50 2.75 2.50 2.75	1000110344 1000113141 1000110344 1000113141 1000113141 1000110344 1000113141 1000110344 1000113141	New 2.0 - 2.5HP 1000111476 Proposed label change: (2.0 - 2.75HP)	No	Digital	No
LS13.0T - C1 LSPRO1 5.1AT	JM12-001	3.00	1000112728	New (unapproved) 2.75 HP 1000111694 Proposed label change: (3.0 HP)	No	Digital	No
LSPRO2 LSPRO3 7.1AT	JM12-003	3.25	1000112527	New (unapproved) 3.0 HP 1000111682 Proposed label change: (3.25HP)	No	Digital	No
CT9.1	JM01-015	2.75	1000113141	Old 2.25 - 2.5HP 032669-IF	Yes	Analog	No
CT12.1 LS13.0T T6	JM12-001 JM12-001 JM12-003	3.00 3.00 3.25	1000112728 1000112728 1000112527	Old 2.75 - 3.0HP 013701-AA	Yes	Analog	No